



**ETN**  
Global

## ETN LM2500 User Group Meeting – GE Session Index

LM2500 Fleet Statistics	1
LM2500 UER Status	8
Compressor	14
HPC Stage 12-14	15
HPC Stage 15	19
HPC Stage 15 & 16 Platform	22
HPC Stage 16 Blade Tip Corner Loss	25
HPC VSV Turnbuckle Wear	26
HPC Stage 9 Air Manifold and Bracket	28
HPT/TMF	30
HPT S1B Durability	31
HPT S1N Windage Cover	34
HPT S2N Cooling Tube	37
HPT S2B Distress	40
Bearings, Seals & Drives	42
IGB Spline Wear	43
IGB Duplex Bearing	47
VSV Torque Shaft Bearings	49
Chip Detector Reliability	50
Oil Debris Monitoring System	51
TMF Seal	54
D-Sump Seal Distress	55
Turbine Rear Frame Oil Leak	56
Combustor	57
CDP Stationary Seal	58
CDP Bleed Valve	61
CAT2 & 3 Items	64
VSV torque shaft bearings	67
HPC Stage 9 Air Manifold and Bracket	68
HPC VSV Turnbuckle Wear	69
C-Ring Manifold Distress	70
Fuel Manifold Bracket Wear	75
HPT S2B Distress	78
T48 Harness	80
Bearing Distress Events	82
Engine Systems	
Control System Package Installation	86
Ventilation	89
Miscellaneous reported issues CAT 2 & 3	93
Sensor Event	94
Calorimeters Reliability	95
FMW – Fuel metering valve cabling	96
Oil system event	97
SeaSmart & LandSmart	98
SeaSmart	99
LandSmart	102
Customization for Offshore	105
Brindisi Shop Update	116